



Modern Machinery Volume 13-14 (Paperback)

By Books Group

Rarebooksclub.com, United States, 2012. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****.This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1903 Excerpt: .But with all his care and watchfulness repairs will be needed and in order to have these done well and promptly when needed, it is highly necessary to keep a first class machinist always at work. Therefore, a small repair shop (not necessarily a small cramped room) containing a lathe, shaper, drill and slotter, pipe threading machine, three or four vises, etc. attached to the engineer s department is always economical. If these are not provided, work that should be done is not always done on account of cost of outside repairing and too often repairs are slighted because of the expense that would be incurred in making them. Editor Modern Machinery: How can I connect an alternating three phase dynamo to the switchboard? R. O, Piano, Texas. To connect an alternating 3 phase dynamo to the switchboard, you connect the 3 terminals on the dynamo...



READ ONLINE

[4.7 MB]

Reviews

Absolutely essential study pdf. It is written in basic words and phrases rather than hard to understand. I am just happy to tell you that this is basically the finest pdf I actually have studied during my personal lifestyle and can be the very best publication for actually.

-- **Shyanne Senger**

Comprehensive information! It's this sort of great go through. It really is really interesting through studying time. I am just quickly can get a satisfaction of looking at a created pdf.

-- **Alexandra Weissnat**